


PRESSURE LOSS DIAGRAM Art.856-858



Q=(l/h)